ECS Configuration (mange Request				Page I of	Į.	Pag	ge(s)	
1. Originator	2. Log Date:	3. CCR#:	1	4. Rev	5. Tel:	6. R	tm #:	7. Dept.	
Layne Behrens	2 ft0 03	00.0	108	_	4162	205	3B	ісотѕ	
8. CCR Title: SGI IRIX 6.2 Patch PSR									
9. Originator Signature/Date			10. Class 11. Ty		11. Type:	12. Need Date: 2/3/2000			
-5/2/2000			7		CCR				
13. Office Manager Signature/Date			14. Category of Change: PSR			15. Priority: (If "Emergency" fill in Block 28). Routine			
16. Documentation/Drawings Impacted: 911-TDA-004 SGI IRIX6.2 O/S Patches, 920- TDG/N/P/V/E/L-014 O/S and COTS Hardware Patch Maps			17. Schedule 18. Cl(s) Affected: mpact:						
			to Customer: 21. Estimated Cos			ost:	est:		
5A, 5B 2/3/20			140tie - Olidei			<u> </u>			
22. Source Reference: NCR (attach) Action Item Tech Ref. GSFC Other: ECSED25243 SGI Leap Year Bug									
	. <u>.</u>		·						
24. Proposed Solution: (use additional sheets if necessary) The SGI IRIX 6.2 Recommended OS, Security, and Y2K Patch UPdates: includes DCE and compiler patches PSR will be distrubuted to all DAACs to patch their IRIX 6.2 hosts. By Tar files: IRIX 6.2 - A 11-12-99. far irix 6.2 - patch 1st - 022 000. tar									
25. Alternate Solution: (use additional sheets if necessary)									
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) There is a y2k leap year bug and secuity vulnerabilities									
27. Justification for Emerg	ency (If Block 15 is "E	mergency"):					•	•	
28. Site(s) Affected: DEDF NOTE NOTE NOTE NOTE NOTE NOTE NOTE NOTE									
	pdate Sec. 5 Fixed on SGI	with NCR	?artio	30. V	Nork Assigned To the he es	0: 31.	CCRC	losed Date:	
32. EDF/SCDV CCB Chair (-, -			`App/Co	m. Disapproved	Withdra	w Fwo	/ESDIS ERB	
Jym V Tuttor 2/4/00 Fwd/ECS 33. Mile CCB Chair (Sign/Date): Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB							VESDIS EDD		
Fwd/ECS						rodio end			
84. ESS CCB Chair (Sign/D		isposition: Ap		App/Cor	n. Disapproved	Withdra	w Fw	d/ESDIS ERB	
, ,		-	/d/ESDIS						

ADDITIONAL SHEET

CCR #: ひょっき Rev: - Originator: Layne Behrens

Telephone: 4162 Office: 2053b

Title of Change: SGI IRIX 6.2 Patch PSR

NCR ID: ECSed25243 Status: MERGED Submitted: 000113
NCR Class: OPERATIONS Project: OPS_COTS Enclosures: 4

NCR TITLE...

SQI Leap Year Bug

PROBLEM INFORMATION...

Build Name[*]: Drop 5A.04

Evaluate Engineer: ebehrens

Test Site[*]: EDF Assigned To: ebehrens

Detected-in-Phase[*]: Code Inspection

Test Case ID: COST ANALYSIS INFORMATION...

Machine Name: Cost[*]: LOW

Severity (1=Showstopper)[*]: 2 Estimated Fix Time(hrs): 2

Mission-Criticality (Admin Use Only): 0 Estimated Fix Date(yymmdd): 000201

Mode [*]: Other Workaround Available? N

Trouble Ticket:

DAAC Trouble Ticket: TO BE FIXED INFORMATION...
SUBMITTER INFORMATION... Problem type[*]: COTS/OS
Submitter: rwhite Recommended change[*]: COTS/OS

Implement Due Date (yymmdd):

Page 1/2

NCR Class: OPERATIONS Project: OPS_COTS

MERGE INFORMATION..
Resolution[*]: COTS/OS
Resolved by: ebehrens
Iteration:
Indicate_SLOC[*]: Not Applicable
Num_SLOC: 0
Fixing time (hrs): 2

Fixing time (hrs): 2 Affect CSCI: all Merge Build Id:

Documentation affected (Y/N)? Y

*********** Problem ************

Please describe the problem you are experiencing below, including what you did, what you expected to happen, and what actually happened:

This bug was reports to us by SGI:

3566: 6.2 all platform kernel rollup System loses day on reboot

Bug Number : 627685
Product : IRIX
Category : software
Classification : bug

Priority Status : 1

Status : closed
Date Opened : 08/12/98

Date Opened
Date Updated

: 08/09/99

Summary

: System loses day on reboot

Description

There is a bug in the software that sets the System Clock from the Real Time Clock (RTC) at boot time.

This problem only occurs on the following systems: Challenge, Onyx, Power Challenge, Power Challenge 10000, Power Onyx, Power Onyx 10000, Origin200, Origin2000 and Onyx2 systems.

The symptoms of this bug depend on the installed system software.

For a system running IRIX 6.2 without patch 2859; or IRIX 6.4 without patch 2980. If the system is rebooted on or between March 1, 1998 and February 28, 2000, the System Clock will be exactly one day slow. This problem recurs for the same period in 2002-2004, 2006-2008, and so on.

For a system running IRIX 6.2 with patch 2859 but not patch 3554; IRIX 6.4 with patch 2980 but not patch 3554; or IRIX 6.5 (base release or 6.5.1 or 6.5.2 overlay releases). This problem occurs when the system is shut down or placed in PROM mode before midnight, February 29, of a leap year, and not rebooted until March 1 or later. When the system is booted, the System Clock will be exactly one day slow.

For a system running IRIX 6.2 with patch 3554 but not patch 3704; IRIX 6.4 with patch 3554 but not patch 3711; IRIX 6.5.3; or IRIX 6.5.4. This problem occurs when the system is shut down or placed in PROM mode before midnight, February 28, of an even-numbered year that is not a leap year, and not rebooted until March 1 or later. When the system is booted, the System Clock will be exactly one day fast.

Workaround:

On rebooting, check the date given by the System Clock. If it is incorrect, set it manually.

************* Resolution (Added 000113 by ebehrens) ************************************						
The SGI patch 3356: 6.2 All Platform Kernel Rollup fixes this problem. A						
for release of this and other os patches in in progress.						
********** Analysis **********						
Please describe your Analysis:						
Problem fixed by patch						
************* Previous Merge Build IDs ***********************************						
Please enter any related Merge Build ID(s) information:						

CM01AJA00